

U. S. Department of Agriculture
FOREST SERVICE

B-22

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 27 Mer.

1/6 NW 1/16 Corner common to Sections
_____, _____, _____, and 1

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Balm

Diameter 16"

Bearing Scribble + facing North

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Presurvey

R. H. Christopher

(Signature)

3-7-57

(Date)

D. H. A.

(Title)

Corner again.
Log - BT on oak
edge of road.
Piper is probably under
a small tree. Distance
to corner is about 100 ft.

Give any further facts which will aid in finding this
chains distant.

from which this Corner bears
side of

tree 6 inches diameter, on the west
Metal Location Poster is on a Ash

	Sec.		Sec.
	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)