

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 & 58 N. R. 27 W. 4th P. Mer.

1/4

Corner common to Sections

1

and 36

Corner consists of a iron pipe & wood stake

State condition good

Dimensions above ground 3/4 x 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4		4	
S		S	
36		1	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	NONE	

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Seth W. Peterson

(Signature)

4/19/38

(Date)

Jr. Asst. to Tech.

(Title)

22-23

(Make sketch of topography near Corner)

	Sec. 36		
		Sec. 1	
	Sec. 35		

T. STANLEY R. 27th. 4th P. Mer.

Metal Location Poster is on a **aspen**

tree **4** inches diameter, on the **SE**

side of **tree**

from which this Corner bears **S. 65° E.**

25 chains distant.

Give any further facts which will aid in finding this

Corner again.

Corner is on top of and on east end of high ridge. Small birch & aspen.