

Rangers
copy

U. S. Department of Agriculture
FOREST SERVICE

N-33

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 27W 4th P.M. Mer.
1/4 Corner common to Sections

24, and 13
Corner consists of a 2x4 Cedar & pipe in place



State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Basswood

Diameter 12"

Bearing N 72° E

Distance 50 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

~~W. H. ...~~


Jim Langan

(Signature)

11/13/36
(Date)

P
(Title)

(Make sketch of topography near Corner)



Metal Location Poster is on a **Basewood**

tree **12** inches diameter, on the **W**

side of **tree**

from which this Corner bears **S 72° W**

0.50 chains distant.

Give any further facts which will aid in finding this

Corner again.

By fence. On sloping hill toward W.

Rangers copy

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 50 N R. 27 W 4 P.M. Mer.

1/4

Corner common to Sections

24

and 13

Corner consists of a 2nd Cedar Pipe (not) in place

State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		1/4	
13		S	
		24	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S13			
B T			

Species Bass

Diameter 12"

Bearing N 72° E

Distance 50 Lks.

Do you believe this to be a genuine Land Office Corner? No

If not, why? Does not agree with G L O

notes. Probably set by county.

Leonard Peterson

(Signature)

11/13/36

(Date)

OGC

(Title)

By fence on sloping hill toward W.

Corner again.

Give any further facts which will aid in finding this


0.50 chains distant.

from which this Corner bears S 72° E

side of 1700

tree 12" inches diameter, on the W

Metal Location Poster is on a Basswood



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

N-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58n R. 27W 5th P. Mer.

1/4 Corner common to Sections 13 24, and

Corner consists of a Cedar post in place



State condition Good

Dimensions above ground 3", 4", 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S.13			
B.T.			

Species Maple

Diameter 10"

Bearing N 72 E.

Distance 50 Links

Do you believe this to be a genuine Land Office Corner? No

If not, why? County corner

C. Fidely
C. Fidely
(Signature)

Leader

(Title)

3/3/41

(Date)

corner

Corner again. Fence runs south and west from the

Give any further facts which will aid in finding this

chains distant.

50


from which this Corner bears

S72° W.

side of Maple tree

tree 10 inches diameter, on the Southwest

Metal Location Poster is on a Maple



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

N-23

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 59 N. R. 27 W. 1 Mer.

1/4 Corner common to Sections
13, and 24

Corner consists of a Tom (~~not~~) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S 24

1/4 S 13

--

--

BT

BT

--

--

Species Sp As (stump)

Diameter 6" 19"

Bearing S 95° W N 22° 30' E

Distance 0.78 0.73

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Sagen
 (Signature)

2-10-39
 (Date)

ccc Enrollee
 (Title)

Handwritten notes on ruled lines, including the word "Aspen" and other illegible text.

Corner again.

Give any further facts which will aid in finding this


0.29 chains distant.

from which this Corner bears N 27 W

side of *Tree*

tree 7 inches diameter, on the NW

Aspen Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 59 N. R. B 27 W. 4 Mer.

Form 874-6—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

N-23

CHIPPWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. **59N** R. **27E** Mer.

Corner common to Sections **13**, and **24**

Corner consists of a **Post** (not) in place



State condition **Good**

Dimensions above ground **30** inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species **Sp** **Aspen (Stump)**

Diameter **6"** **14"**

Bearing **S45E** **S82°30'E**

Distance **0.75** **0.73**

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Larson

Jan 17. '35

Geo. Larlee

(Date)

(Title)

May 4, 1960. Spruce 6" B.I. is dead, but standing. C.T.S. on west side of a woods road. Could not locate the corner post. *gpk*

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.29

from which this Corner bears

27N

side of


Tree

tree 7 inches diameter, on the

W

Metal Location Poster is on a

Aspen



(Make sketch of location by near Corner)

U. S. Department of Agriculture

FOREST SERVICE

CELINA

NATIONAL FOREST

N-23

CORNERS OF THE PUBLIC SURVEY

T. 59th R. 27th Mer.

Corner common to Sections

13, and 26

Corner consists of a ~~stone~~ (not) in place

Good



State condition

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of in located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

2-11-13

Geo. H. ...

(Date)

(Title)

Blank lined area for notes at the top of the page.

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears

side of

tree 7 inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Supervisor's copy

U. S. Department of Agriculture
FOREST SERVICE

N 23
P

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. ~~58 N~~ R. ~~27 W~~ ~~4 P.M.~~ Mer.

~~1/4~~ Corner common to Sections
~~24~~, and ~~13~~

Corner consists of a ~~2x4 Cedar & Pipe~~ (not) in place

State condition ~~good~~

Dimensions above ground ~~36~~ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		1/4	
13		S	
		24	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4			
S 13			
B T			

Species ~~Bass~~ _____

Diameter ~~12"~~ _____

Bearing ~~N 72° E~~ _____

Distance ~~50 Lks.~~ _____

Do you believe this to be a genuine Land Office Corner? ~~No~~

If not, why? ~~Does not agree with G L O~~

~~notes. Probably set by county.~~


~~Leonard Peterson~~
(Signature)

~~11/13/36~~
(Date)

~~000~~ (Title)

(Make sketch of topography near Corner)

T. 68 N R. 27 W 4 P.M. Mer.



Metal Location Poster is on a **postwood**

tree **12"** inches diameter, on the **W**

side of **Tree**

from which this Corner bears **S 72° N**

0.50

chains distant.

Give any further facts which will aid in finding this

Corner again.

By fence on sloping hill toward W.

U. S. Department of Agriculture

FOREST SERVICE

N-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 29N R. 27W 4 Mer.

1/4 Corner common to Sections 13, and 24

Corner consists of a post (not) in place


State condition Good

Dimensions above ground 30 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Sp. Aspen (stump)

Diameter 6" 14"

Bearing S45W N22°30'E

Distance 0.72 0.73

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

M. J. S. C. N. (Signature)

Jan 17 '25 (Date)

C. C. C. Enrollee (Title)

Corner again.

Give any further facts which will aid in finding this


0.29 chains distant.

from which this Corner bears N 27 W

side of tree

tree 7 inches diameter, on the NW

Metal Location Poster is on a ~~tree~~ *Aspen*



(Make sketch of topography near Corner)

T. 59 N. R. 27 W. Mer. 4