

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

E-93

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 27 Mer.

Corner common to Sections
1, and 12

Corner consists of a I.P.P. (not) in place
State condition good

Dimensions above ground 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|---|---|---|---|
| | | | |
| N | W | S | E |

| | | | |
|----|----|----|----|
| | | | |
| NW | SW | SE | NE |

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|----------------|--|----------------|--|
| <u>Scribed</u> | | <u>Scribed</u> | |
| | | <u>rotted</u> | |
| | | <u>off</u> | |

Species Ash Ash
Diameter 7" 7"
Bearing N 85° E N 85° W
Distance 20 FT 8

Do you believe this to be a genuine Land Office Corner? No

If not, why? Presurvey

R. H. Christopher

(Signature)

DER

(Title)

1-5-55

(Date)

Control top up on
Swami Road and on logging of
Road 15 chs or so west of
corner

Corner again.
I in oak 500-100 - line
blazed N and West

Give any further facts which will aid in finding this

6 feet chains distant.

from which this Corner bears


N-70

side of

tree 6 inches diameter, on the

Metal Location Poster is on a

Ash



(Make sketch of topography near Corner)