

U. S. Department of Agriculture

FOREST SERVICE

God

Chippewa NATIONAL FOREST v24

CORNERS OF THE PUBLIC SURVEY

T. 58 N. R. 27 W. 4th Mer.

E 1/16 Corner common to Sections

25, and 36

Corner consists of a 4" white Post in place

State condition 1" iron pipe good

Dimensions above ground 3' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 25		S 36	
---------	--	---------	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? Note; no B.T.

Ervin Meagher

(Signature)

12/12/34


(Date)

Field Asst.

(Title)

Corner again.
 CORNER IS 3.55 CHAINS
 east of SPURCE swamp.

Give any further facts which will aid in finding this
 chains distant. 1.16
 from which this Corner bears 578°W
 side of tree
 tree 8" inches diameter, on the SW
 Metal Location Poster is on a Maple



(Make sketch of topography near Corner)

T. 58 N. R. 27 W. 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

10-1

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 58 N. R. 27 W. 4th Mer.

E 1/16 Corner common to Sections
25, and 36

Corner consists of a 4" white pine (not) in place
1" iron pipe
State condition good

Dimensions above ground 3' high inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 25		S 36	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? Note; no B.T.

Ervin Meagher

(Signature)

12/12/34

(Date)

Field Asst.


(Title)

Corner again.
Corner is 3.55 chains
east of spruce swamp

Give any further facts which will aid in finding this
chains distant. 1.16

From which this Corner bears 5 48' W
side of Tree

Metal Location Poster is on a Maple
tree 8" inches diameter, on the S W



(Make sketch of topography near Corner)

T. R. Mer.

(D)

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

14-1
42-1

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 58 N. R. 27 W. 4th Mer.

E. 1/16 Corner common to Sections
25, and 36

Corner consists of a 4" white pine (not) in place
iron pipe
State condition good

Dimensions above ground 3' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 25		S 36	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? Note; no B.T.

Ervin Meagher

(Signature)

Field Asst.

12/12/34

(Date)


(Title)

Corner again.
Corner is 3.55 chains
east of spruce swamp

Give any further facts which will aid in finding this
1.16 chains distant.

From which this Corner bears
S. 48° W.

side of Tree
8" inches diameter, on the S.W.
Metal Location Poster is on a Maple



(Make sketch of topography near Corner)

T. 58 N. R. 27 W. 4th Mer.