

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

P
N24

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 27 W 4 P.M. Mer.
E 1/16

Corner common to Sections
14, and 23

Corner consists of a 4" cedar & pipe (not) in place
State condition good

Dimensions above ground 42" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

E 1/16 S 14	W 1/16 S 14	E 1/16 S 14	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

E 1/16 S 23	E 1/16 S 14		
B T	B T		

Species Birch stub Birch stub
Diameter 8" 7"
Bearing S 37° E N 24° W
Distance 16 links 8 1/2 links

Do you believe this to be a genuine Land Office Corner? No
If not, why? No 1/16 corners set here by G. L. O. probably County corner.

Leonard Peterson

(Signature)

11/12/36


(Date)

CCC

(Title)

(Make sketch of topography near Corner)

T. 58 N R. 27 W S.P.M. Mer.



Metal Location Poster is on a Birch

tree 8 inches diameter, on the N

side of hill

from which this Corner bears N 37° W

0.16

chains distant.

Give any further facts which will aid in finding this Corner again.

In Nelson swamp light brush.

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

46-N

CHIPPEWA NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. **58N** R. **27W** 5th Mer.
 E **1/16** Corner common to Sections
13 **24**, and

Corner consists of a **cedar** (not) in place
 State condition **Good**

Dimensions above ground **4" sq X 30"** inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		E 1/16	
13		S 24	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Do you believe this to be a genuine Land Office Corner? **NO**
 If not, why? **county corner**


C. Fidelity
C. Fidelity
 (Signature)

5/4/41
 (Date)

(Title)

(Make sketch of topography near Corner)

T. 58N R. 27W 5th P Mer.



Metal Location Poster is on a Ash

tree 8 inches diameter, on the South West

side of Ash tree

from which this Corner bears S. 42° W.

chains distant.

Give any further facts which will aid in finding this

Corner again.

ences ends at corner.

U. S. Department of Agriculture
FOREST SERVICE

1-24

Shippen NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 58 R. 27 4 Mer.

E 1/16 Corner common to Sections

14, and 23
Corner consists of a 4" Cedar + 1 1/2" x 8" (not) in place

State condition good

Dimensions above ground 42 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

E 1/16	E 1/16
S	S
14	23

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

E 1/16	E 1/16		
S 23	S 14		
BT	BT		

Species Birch 5 1/2" Birch 3 1/2"

Diameter 8" 7"

Bearing S 37° E N 24° W

Distance 16 1/2 8 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

INCORRECT

Leonard Peterson

(Signature)

11/12/36
(Date)


(Title)

Corner again. *I N Balsam Swamp - light brush*

Give any further facts which will aid in finding this chains distant.

from which this Corner bears *N 37° W* side of *tree*

tree *8* inches diameter, on the *N* Metal Location Poster is on a *B 15 ch*



(Make sketch of topography near Corner)

T. 58 N. R. 37 W. Mer. 4

Rangus copy

U. S. Department of Agriculture
FOREST SERVICE

2-24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 27 E 4 P.M. Mer.
E 1/16

Corner common to Sections

18, and 24

Corner consists of a 4" cedar & pipe (not) in place
State condition good

Dimensions above ground 42" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

E 1/16 S 14	E 1/16 S 14	E 1/16 S 14	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

E 1/16
S 23

E 1/16
S 14

B T

B T

Species Birch stub Birch stub

Diameter 8" 7"

Bearing S 37° E N 24° W

Distance 16 links 8 1/2 links

Do you believe this to be a genuine Land Office Corner? No

If not, why? No 1/16 corners set here by G. L. O. Probably County corner.

Leonard Peterson

(Signature)

11/12/36

(Date)

COO

(Title)

In Balance Swamp Light Bush.

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.16


from which this Corner bears N 37° W

side of

hill

tree 8 inches diameter, on the N

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 39 N R. 27 W S. 4 P.M. Mer.