

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

C-24

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 27 Mer.

Int. E. to Corner common to Sections
1, _____, _____, and _____

Corner consists of a Iron Pipe (not) in place
State condition good

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Passing

R. H. Chumley

(Signature)

3-6-57
(Date)

D. E. P.
(Title)

Corner again.
Inset and 5" post
Post is under a bush
in the field

Give any further facts which will aid in finding this
from which this Corner bears *N 40 W*
side of *15 feet* chains distant.
tree *4* inches diameter, on the
Metal Location Poster is on a *1 1/2 in*

	Sec.	Sec.	
	Sec.	Sec. / (6)	

(Make sketch of topography near Corner)