

Camp copy

6

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

Y-25

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

S. T. <sup>53</sup> 1/16 on range <sup>26-27</sup> 1120 Mer. 4

Corner common to Sections

31 and 36

Corner consists of a ~~stone~~ (not) in place

State condition

Dimensions above ground ~~61 by 38~~ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<sup>1</sup> 16		<sup>1</sup> 16
	31		36


N W S E NW SW SE NE

Mound of ~~none~~ is located ~~none~~

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why? 1/16 corner not in original survey.

*A. Broadbridge*

6/24/36

foreman of survey crew

(Date)

*W. M. M.*

Iron pipe two inches above the ground.

Corner again.


Give any further facts which will aid in finding this chains distant.

from which this Corner bears.

side of the line

tree. inches diameter, on the east

Metal Location Poster is on a



(Make sketch of topography near Corner)