

camp copy

6

U. S. Department of Agriculture

FOREST SERVICE

W-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 53 R. 26-27 Mer.

N. 1/16 on range line Corner common to Sections

31, 32, 33, and 34, T. 53, R. 27

Corner consists of a Tamarack (not) in place

State condition Good

Dimensions above ground 6x4 by 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/16	1/16
31	33

N W S E

NW SW SE NE

Mound of none is located

Pits are located none

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--	--	--	--

BT			
----	--	--	--

Species Spruce stump

Diameter 9"

Bearing N. 30 W.

Distance 26

Do you believe this to be a genuine Land Office Corner No.


If not, why? 1/16 corner not in original survey. 30" stake and iron pipe 6" high.

Robert Broadbridge (Signature)

Foreman of survey crew (Title)

6/24/30 (Date)

Corner again.
 About the center of 7. b. 5. 5. 5.
 and two chains north of old location.
 Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree. inches diameter, on the
 Metal Location Poster is on a
 spruce



(Make sketch of topography near Corner)