

U. S. Department of Agriculture

FOREST SERVICE

52525  
52525

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 ~~28~~ R. 29 ~~20~~<sup>27</sup> 4 Mer.

~~46 #7~~ N 1/16 Corner common to Sections 30, and 25 57-27

Corner consists of a Cedar - 5" (not) in place State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch, stump Cedar

Diameter 14" 8"

Bearing S 84° W N 51° W

Distance 25 ch. 66 ch.

Do you believe this to be a genuine Land Office Corner No.

If not, why? County resurvey corner.

(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

R.

T.