

U. S. Department of Agriculture
FOREST SERVICE

2-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 52N R. 27E 26E 4E Mer.

1/4

Corner common to Sections

13

18

, and

Corner consists of a Tomato (oil) in place

State condition Fair

Dimensions above ground 4" x 2 1/2" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

<u>1/4</u>		<u>1/4</u>	
<u>S.13</u>		<u>S.18</u>	

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u>
<u>S.13</u>

<u>1/4</u>
<u>S.</u>

--

--

<u>B.T.</u>

<u>B.T.</u>

--

--

Species Tom. Tom.

Diameter 4" 3"

Bearing N51 1/2° W S23 1/2° E

Distance .26 .59

Do you believe this to be a genuine Land Office Corner? NO


If not, why? County corner

C. Fidelity
C. Fidelity
(Signature)

Inspector
(Title)

3/5/41
(Date)

(Make sketch of topography near Corner)



Metal Location Poster is on a **Tamarack**

tree 4 inches diameter, on the **Southeast**

side of **Tamarack**

from which this Corner bears

N 1 1/2 W

chains distant.

Give any further facts which will aid in finding this

Corner again.

In tamarack sapling swamp