

Pringlers
1937

U. S. Department of Agriculture
FOREST SERVICE

X-2

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N. R. 26 W. 4th Mer.

N-center 1/16 Corner common to Sections
31, , and

Corner consists of a Cedar Post (not) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16 # 4

1/16 # 4

--

--

BT

BT

--

--

Species B. Gillies Aspens

Diameter 13" 9"

Bearing N41°E S6E

Distance 91ks 50ks

Do you believe this to be a genuine Land Office Corner? No

If not, why?

Corner Post set by county
SURVEYORS

J. C. Murbeck

(Signature)

12/2/36

(Date)

(Title)

Corner again.
 Corner located about a chains
 north of T. T. 591. The Alder
 to Sweeny road.
 Timber has been cleared
 around this corner and
 small Respa + Brush has grown
 up. Some balsam about 1 chain
 south.

Give any further facts which will aid in finding this

50 LKS ~~chains~~ distant.
 from which this Corner bears

N 6 W


side of Tree

tree 9 inches diameter, on the

North

Metal Location Poster is on a

48 p.m



(Make sketch of topography near Corner)

T. 591 R. 26 W. 4th Mer.

Supervisors
copy

U. S. Department of Agriculture

FOREST SERVICE

X-2

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 9th Mer.

W-Center 1/16 Corner common to Sections 31, _____, and _____



Corner consists of a 4" Cedar Post (not) in place
State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16
#4

1/16
#4

BT

BT

Species B. Gullard Aspen

Diameter 12" 9"

Bearing N 41° E S 6 E

Distance 91 Lks 50 Lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Corner set by county surveyors and bearing trees scribed by same

J. C. Murbeck

(Signature)

12/2/36

(Date)

(Title)

Corner located about 2 chains north of T. 59. The alders to Suomi road. Timber has been cleared around this corner, and timber is mostly small aspen and brush. ~~Some~~ Balsam about chain south

Corner again.

Give any further facts which will aid in finding this

50 lks ~~about~~ distant.

from which this Corner bears


N 6 W

side of Tree

tree 9 inches diameter, on the north

Metal Location Poster is on a

Aspen



(Make sketch of topography near Corner)

T. 59 N R. 26 W 9th Mer.