

2097

U. S. Department of Agriculture

FOREST SERVICE

Y-4

Shippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

SE 1/16 or # 7 Corner common to sections 31, , and

Corner consists of a Cedar Post - iron spike (not) in place


State condition Good

Dimensions above ground 30 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Gilead Aspen

Diameter 8 12

Bearing N11W S47E

Distance 31 Lks 21 Lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Corner set by county

Surveyors and bearing trees

Scribed by same

(Signature)

10/22/36

(Date)

(Title)

Timber Type: Balsam-Aspen
Approx. 3 chs north is a clearing
Also F.S. Post set at corner.

Corner again.

Give any further facts which will aid in finding this


211K5 ~~chain~~ distant.

from which this Corner bears N47W

side of Tree

tree 13 inches diameter, on the West

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4th Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa

NATIONAL FOREST

Y-4

P

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 20 W Mer. 4

SE 1/16 # 7 Corner common to Sections

_____, 31, and _____

Corner consists of a cedar post - iron pipe (not) in place

State condition good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/16 # 7</u>

<u>1/16 # 7</u>

--

--

<u>BT</u>

<u>BT</u>

--

--

Species B. Felled log

Diameter 8"

Bearing N 11 W S 47 E

Distance 31 lks 21 lks

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Resurvey of county

(Signature)

(Date)

(Title)

3000 m of corn & a clearing
Top
Barham - Capra

Corner again.

Give any further facts which will aid in finding this

At the chains distant.


from which this Corner bears *N 47 W*

side of *see*

tree *13* inches diameter, on the

Capra
N 47 W

Metallod position Poster is on a



RECEIVED
JUL 14 1937
CASS LAKE, MINN.

Ontario - Metrolod Poster
CASS LAKE, MINN.

(Make sketch of topography near Corner)

T. 59 N. R. 26 W. 7 Mer.