

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *59 N* R. *26 W* *7 1/2* Mer.

1/16 # 8

Corner common to Sections

31, and

Corner consists of a *Calagat-iron pipe* (not) in place

State condition *good*

Dimensions above ground *20* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		S	
31		31	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>1/16</i>			
<i>BT</i>	<i>BT</i>		

Species *Spruce Balsam*

Diameter *6"* *7"*

Bearing *N38° E* *S88.33° E*

Distance *10 lks* *3 1/2 lks*

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Re-surveyed by county


Murdoch - Mielbauer
(Signature)

10/2/20
(Date)

(Title)

Corner again.
Type from above corner
Mary to Holt + West
Dress cleaning 2 do no of corner

Give any further facts which will aid in finding this
chains distant.
/10
from which this Corner bears
side of
tree 6 inches diameter, on the
Metal Location Poster is on a
D 38 N



(Make sketch of topography near Corner)

T. 59 N. R. 26 W. 4th Mer.

POST SERVICE

camp copy

U. S. Department of Agriculture

FOREST SERVICE

X-4

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N. R. 26 W. 4th Mer.

E-Section 1/16 or #8 Corner common to Sections 31, and

Corner consists of a Cedar Post-iron (not) in place

State condition Good

Dimensions above ground 30 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Spruce Balsam

Diameter 6 7

Bearing N38E S88.30E

Distance 101KS 31 1/2 KS

Do you believe this to be a genuine Land Office Corner? No

If not, why? Corner set by county

Surveyors & scribed by same

Murbeck (Signature)


10/22/36

(Date)

(Title)

Corner again.
 County corner + pipe in place
 small clearing & pipe in north
 of corner
 4 inch type spruce
 sapling
 downy cone to north
 and west.

Give any further facts which will aid in finding this
 10 links. check distant.
 from which this Corner bears S 38 W
 side of Tree
 tree 6 inches diameter, on the SW
 Metal Location Poster is on a S P 1/4 Sec 3



(Make sketch of topography near Corner)