

U. S. Department of Agriculture

FOREST SERVICE

F-4

Original Copy

23

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

1/16 # 7 Corner common to sections

7, and

Corner consists of a 4" Balsam iron pipe (not) in place


State condition Good

Dimensions above ground 36 x 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Maple Maple

Diameter 8" 10"

Bearing N45°E N47°W

Distance 19 lks 62 lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Corners located by County

S.P. Survey

Data taken from CCC Survey Notes

by P. B. Centerwall

(Signature)

7/15/37 (Date)

JUN. FAIRBANKS (Title)


F-1

Corner again.
Found nothing - Mapk found
and logs built

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree 8 inches diameter, on the
Metal Location Poster is on a
Mapk

S 1/5 W

NE



(Make sketch of topography near Corner)

T. 57 N R. 26 W Mer. 47

U. S. Department of Agriculture
FOREST SERVICE

F-4

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *57* R. *26* Mer. *4*

1/16 # 6 Corner common to Sections

and *7*, and
Corner consists of a *4" Belman + 10" Iron pipe* (not) a place


State condition *Good.*

Dimensions above ground *36* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Maple* *Maple*
Diameter *8"* *10"*
Bearing *N45°E* *N47°W*
Distance *.19 ch.* *.62 ch.*

Do you believe this to be a genuine Land Office Corner? *no*
If not, why? *Corner located by County resurvey.*

(Signature)

(Date)

(Title)

F-4

Corner again.
Lead rolling, iron
marks, movement + marks.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears ^{19'} ~~19545m~~

side of Corner

tree 8 inches diameter, on the NE

Metal Location Poster is on a ^{Maple}



(Make sketch of topography near Corner)

T. 57 R. 26 Mer. 4