

Revised 1911

U. S. Department of Agriculture

FOREST SERVICE

T-5

Chryseus NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *59 N* R. *26 W* *4/18* Mer.

1/4 Corner common to Sections

29, and *30*

Corner consists of a *Cedar post 3 1/2'* (not) in place

State condition *good*

Dimensions above ground *3.0* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species *Maple Sugar*

Diameter *6"*

Bearing *S 91° W*

Distance *65.1 Ks*

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *County records*

Data taken from CCC Survey notes

P. B. Centennial

(Signature)

7/15/37
(Date)

Gen. Forester
(Title)

J. C. Murbeck

not a metal location post
Corner again.

Give any further facts which will aid in finding this
chains distant.
From which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R. Mer.

Supervisor 2-27-17

U. S. Department of Agriculture
FOREST SERVICE

T-5 P

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *59 N* R. *26 W* *4th* Mer.

1/4 Corner common to Sections
29, and *30*



Corner consists of a *cadogan post 3 1/2"* (not) in place
State condition *good*

Dimensions above ground *30* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Myrt. Sweet* _____

Diameter *6"* _____

Bearing *S 41° W* _____

Distance *65/165* _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

County Assessor

Data taken from CCC Survey notes

H. P. B. Centerville

(Signature)

7/15/37
(Date)

Jun Forester
(Title)

T.

R.

Mer.

(Make sketch of topography near Corner)

RECEIVED
 APR 13 1937
 NATIONAL BUREAU OF
 GEOSYMBOLS
 CASI LAKE, MINN.

Metal Location Poster is on a tree inches diameter, on the side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.

No metal location given just report