

U. S. Department of Agriculture

FOREST SERVICE

F-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th P Mer.

N 1/4

Corner common to Sections

7, and 8

Corner consists of a (not) in place


State condition

Dimensions above ground inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

George H Jennings (Signature)


8-7-35 (Date)

Coast Range (Title)

.....

Corner again
 On edge of small
 thick lot balsam.

Give any further facts which will aid in finding this
 chains distant.
 0.10
 from which this Corner bears
 570° E
 side of tree
 5 inches diameter, on the SE
 Metal Location Poster is on a W. Birch



(Make sketch of topography near Corner)

T. 59 N. R. 26 W. 4th P Mer.