

U. S. Department of Agriculture
FOREST SERVICE

L-7

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W S. 9 Mer.

Center 1/4 Corner common to Sections
17, _____, _____, and _____

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____
Diameter _____
Bearing _____
Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____


George J. Jennings
(Signature)

8-12-35
(Date)

Const. Foreman C. M.
(Title)

Corner again.
Opposite small borrow
pit on N side of road

Give any further facts which will aid in finding this
chains distant.
108
from which this Corner bears
side of pole
tree inches diameter, on the NW
Metal Location Poster is on a
Tel. pole



(Make sketch of topography near Corner)

T. 59 N. R. 26 W. 4 Mer.