

U. S. Department of Agriculture

FOREST SERVICE

J-7 Y

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th P. Mer.

1/4 Corner common to Sections

8, and 17

Corner consists of a 4" cedar (not) a place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4		1/4	
S		S	
8		17	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S 8		1/4 S 8	
BT		BT	

Species Cedar Cedar

Diameter 7 7

Bearing N67W S45E

Distance 0.24 0.29

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Old stake present. New stake set by Co. Surveyor on 7-31-35

George H. Jennings

(Signature)

8-1-35

(Date)

Const Foreman C & M

(Title)

Corner again.

Give any further facts which will aid in finding this


0.24 chains distant.

from which this Corner bears S67E

side of tree

tree 7 inches diameter, on the SE

Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

J-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W Sta P. Mer.

1/2

Corner common to Sections

8, and 17

Corner consists of a 4 cedar (not) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4		1/4	
5		3	
8		17	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 5 8		1/4 3 17	
BT		1ST	

Species Cedar Cedar

Diameter 7 7

Bearing N67W S45E

Distance 0.25 0.29

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Old stake, present N-W stake set by Co. Surveyor on 7-31-35

George H. Jennings (Signature)

8-1-35 (Date)

Const. American C. M. (Title)

Corner again.

Give any further facts which will aid in finding this

chains distant

0.24

from which this Corner bears

S67E

side of


tree

tree 7 inches diameter, on the

S1E

Metal Location Poster is on a

Cedar



(Make sketch of topography near Corner)

T. 59N R. 26W 4th P. Mer.