

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 4 Mer.

1/16 # 7 SE 1/16 Corner common to Sections

and 20

Corner consists of a 4.5 square iron pin (not) in place

State condition good

Dimensions above ground 30" post - 12" pin inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species WP WP

Diameter 7" 5"

Bearing N61°E 523°W

Distance .34 ch. .38 ch

Do you believe this to be a genuine Land Office Corner? No

If not, why? County survey

(Signature)

(Date)

(Title)

Metal Location Poster is on a \_\_\_\_\_  
 tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_  
 side of \_\_\_\_\_  
 from which this Corner bears \_\_\_\_\_  
 chains distant.

Give any further facts which will aid in finding this  
 Corner again.

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)