

U. S. Department of Agriculture

FOREST SERVICE

E-8

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 Mer.E 1/16

Corner common to Sections

5, and 8

Corner consists of a _____ (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? YesIf not, why? U.S.F.S.

(Signature)

(Date)

(Title)

12-4-35

[Faint, illegible handwriting on ruled lines]


South side of road
Corner again.

Give any further facts which will aid in finding this
chains distant.

9.36
from which this Corner bears
NSW

side of *tree*
A inches diameter, on the
N

B. Ash
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. R. Mer.