

## U. S. Department of Agriculture

FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

R-9

## CORNERS OF THE PUBLIC SURVEY

T. 59.N. R. 26.W. 4<sup>th</sup> Mer.

section Corner common to Sections

20, 21, 22, and 23

Corner consists of a 5" cedar post (not) in place  
1/4" iron pipe.  
State condition goodDimensions above ground post 36" pipe 8 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S. 20	S. 29	S. 28	S. 21
-------	-------	-------	-------

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 20	S. 29	S. 28	S. 21
-------	-------	-------	-------

B.T.	B.T.	B.T.	
------	------	------	--

Species aspen aspen aspen

Diameter 10" 9" 8"

Bearing N. 55° W. S. 45° W. S. 47° E.

Distance 57 links 12 links 98 links

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Ernest Perry  
(Signature)  
Field Ass't.  
(Title)12-21-34  
(Date)

Section corner is located 8 chains south of Camp Idlewild

Corner again.

Give any further facts which will aid in finding this


12 inch ~~chain~~ distant.

from which this Corner bears N 45° E

side of tree

tree 2 inches diameter, on the N.E.

Metal Location Poster is on a S.W. B.T.



(Make sketch of topography near Corner)

T. 59 N. R. 26 W. 4th Mer.

Form 874-8—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

R-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N. R. 26 W. 4<sup>th</sup> Mer.

section Corner common to Sections

20, 21, 28, and 29

Corner consists of a 5" cedar post (not) in place

State condition good <sup>3/4" iron pipe</sup>

Dimensions above ground post 36" pipe 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S. 20	S. 29	S. 28	S. 21
-------	-------	-------	-------

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 20	S. 29	S. 28	S. 21
B.T.	B.T.	B.T.	

Species aspen aspen aspen

Diameter 10" 9" 8"

Bearing N. 55° W. S. 45° W. S. 43° E.

Distance 57 links 19 links 98 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

12-21-34.  
(Date)

Ernest Perry  
(Signature)  
Field Asst.  
(Title)

Section corner is located  
8 chains south of camp, middle wild

Corner again.

Give any further facts which will aid in finding this


19 1/2 chains distant.

from which this Corner bears N 45° E

side of tree

tree 9 inches diameter, on the N.E.

Metal Location Poster is on a S.W. BT.



(Make sketch of topography near Corner)