

U. S. Department of Agriculture

FOREST SERVICE

N-98

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th P. Mer.

Sec.

Corner common to Sections

16, 17, 20, and 21

Corner consists of a 4" cedar stake (not) in place

State condition good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S	S	S	S
17	20	21	16

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? Co. Corner 3 yrs. old

George H. Jennings

(Signature)

8-8-35

(Date)

Const. Foreman C&M

(Title)

On fence corner

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.56

S37E

from which this Corner bears


side of tree

tree 6 inches diameter, on the

SE

Metal Location Poster is on a

Aspen



(Make sketch of topography near Corner)

T. 59N R. 26W 4P Mer.

02506
These
is wrong

U. S. Department of Agriculture
FOREST SERVICE

N-9

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N. R. 26 W. 4th Mer.

Section Corner common to Sections

16, 17, 20, and 21

Corner consists of a 5" cedar post (not) in place

State condition good
3 cornered iron pin

Dimensions above ground post 36" pin 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S. 17		S. 20	
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 17

S. 20

B.T.

B.T.

Species ASPEN

W. cedar

Diameter 5"

5"

Bearing N. 37° W.

S. 97° E.

Distance 57 links

154 links

Do you believe this to be a genuine Land Office Corner? NO

If not, why? COUNTY RESURREY CO. R.

Ernest Perry

(Signature)

Field Asst.

(Title)

5-15-35

(Date)

Corner again.

Give any further facts which will aid in finding this


154 link chains distant.

from which this Corner bears *N 47° W*

side of *tree*

tree *5* inches diameter, on the *NW*

Metal Location Poster is on a *W Cedar*



(Make sketch of topography near Corner)

T. 59 N. R. 26 W. 4th Mer.

U. S. Department of Agriculture

FOREST SERVICE

N-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th P Mer.

300 Corner common to Sections

16, 17, 20, and 21
Corner consists of a 4" Galv St (net) in place

State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

5	5	5	5
17	20	21	16

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? C6. Corner, 3 yrs. old.

George H. Jennings

(Signature)

8-8-35

(Date)

Forest Ranger

(Title)

On fence corner

Corner again.

Give any further facts which will aid in finding this


0.56 chains distant.

from which this Corner bears *537E*

side of *tree*

tree *6* inches diameter, on the *SE*

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)

T. 59N R. 26W 4 P Mer.