

U. S. Department of Agriculture

FOREST SERVICE

Chippewa

NATIONAL FOREST

J-9A

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th PM Mer.

Section

8 9 16 17

Corner common to Sections

and

Corner consists of a 2 x 2 (not) n place

State condition Good

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

8	17	16	9
---	----	----	---

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		S 16	
		S T	

Species	Cedar	Cedar
Diameter	12	10"
Bearing	N20W	S30E
Distance	10ch	0.32

Do you believe this to be a genuine Land Office Corner? No

If not, why? Just placed by Co.

Surveyor 7-30-35

George H. Jennings

7-31-35


Const. Foreman. C & M

(Date)

(Title)

Corner again.
 About 0.05 chs from fence
 corner.
 Give any further facts which will aid in finding this

0.10 chains distant.
 from which this Corner bears S 20° E
 side of tree 12 inches diameter, on the SE tree
 Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

J-9

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th PM Mer.

Section Corner common to Sections 5, 9, 16, and 17

Corner consists of a 2 x 2 (not) in place

State condition Good

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

8	17	16	9
---	----	----	---

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		5 16	
		BT	

Species Cedar

Diameter 12 10"

Bearing N20W S30E

Distance 10.24 0.32

Do you believe this to be a genuine Land Office Corner? No

If not, why? Just placed by Co

Surveyor 7-30-31

George R. (Signature)


7-31-35 (Date)

Const. Foreman (Title)

.....
.....
.....
.....
.....

Corner again.
About 0.5 chs from
fence corner.

Give any further facts which will aid in finding this
chains distant.
0:10
from which this Corner bears
S 20° E
side of
tree 12 inches diameter, on the
Metal Location Poster is on a
Cedar



(Make sketch of topography near Corner)