

U. S. Department of Agriculture

FOREST SERVICE

3-10

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N. R. 26 W. 4th P. Mer.

~~XII~~ 116 Corner common to Sections
 _____, _____, 9, and 16

Corner consists of a _____ (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
 fill blanks below, giving bearings from Corner to Trees and
 Distances in Links.

Species BalsamDiameter 8Bearing S15EDistance 0.43 ch.

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

George H. Jennings

 (Signature)

7-79-35 Const. Abraham C. M.


 (Date) (Title)

Corner again.
 52 chs. Not brushed
 line. Near fence

Give any further facts which will aid in finding this
 D. 43 chains distant.

from which this Corner bears
 N 15 W

side of
 B. Tree
 tree 8 inches diameter, on the
 S E
 Metal Location Poster is on a
 Balsam



(Make sketch of topography near Corner)

T. 59 N R. 25 W Mer.