

U. S. Department of Agriculture

FOREST SERVICE

Pa. 1st

Chippewa NATIONAL FOREST U-11

CORNERS OF THE PUBLIC SURVEY

T. *59 N* R. *26 W* *4th* Mer.

6 *V16* Corner common to Sections

_____, _____, *28*, and _____

Corner consists of a *4" cedar* (~~rod~~) in place

State condition *good* (*1" iron pipe 6"*)

Dimensions above ground *3'* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	# 6		# 6
--	--------	--	--------

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	# 6		# 6
	B.T		B.T

Species *Aspen* *Aspen*

Diameter *5"* *4"*

Bearing *N 33° E* *S 51° E*

Distance *51 Li* *35 Li*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Ermin Meagher
(Signature)

1-7-35
(Date)

Field Ass't
(Title)

LAND LEVEL SECOND GROWTH ASPEN

Corner again.


Give any further facts which will aid in finding this

35 L. chains distant.

from which this Corner bears N 51° W

side of tree

tree 4 inches diameter, on the N.W. ASPEN Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4th Mer.