

U. S. Department of Agriculture
FOREST SERVICE

A-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 & 60 R. 26 W 4th P Mer.

1/4 Corner common to Sections
33, 2, and 4

Corner consists of a stake (not) in place
State condition _____

Dimensions above ground 30 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? U.S.F.S. 0

9-23-35
(Date)


(Signature)
Const. Jore, et al
(Title)

Corner again. 35 ft. N. of picket line

Give any further facts which will aid in finding this
0.25 chains distant.

From which this Corner bears
side of *tree*

tree 4 inches diameter, on the
Metal Location Poster is on a *Maple*



(Make sketch of topography near Corner)

T. 59860 R. 26 4th P Mer.