

U. S. Department of Agriculture  
FOREST SERVICE

B-12

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th P Mer.

NE 1/4 Corner common to Sections  
\_\_\_\_\_, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a Aspen Stake (set) in place  
State condition \_\_\_\_\_

Dimensions above ground 30 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? U.S.F.S.

George J. Jennings  
(Signature)

9-23-35  
(Date)

Const. Doer C. M.  
(Title)


-----  
-----  
-----  
-----  
-----  
-----  
-----

Corner again: About 100' North of Ethel Lake

Give any further facts which will aid in finding this chains distant. 0.13

from which this Corner bears 530° W side of tree

tree 3 inches diameter, on the SW Metal Location Poster is on a Maple



(Make sketch of topography near Corner)

T. 59 R. 25 4th P Mer.