

U. S. Department of Agriculture

FOREST SERVICE

A-12

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 & 60 R. 26 W 4th P Mer.

E 1/4

Corner common to Sections

4 and 33

Corner consists of a Cedar stake (not) in place

State condition

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? U.S.F.S.

George H. Jennings

(Signature)

9-23-35

(Date)

Const. Insp. C.M.

(Title)

Lined writing area with horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.11

from which this Corner bears

S45°W

side of


tree

tree 4 inches diameter, on the

SW

Metal Location Poster is on a

W Birch



(Make sketch of topography near Corner)

T. 59+00 R. 20W 44 P Mer.