

U. S. Department of Agriculture

FOREST SERVICE

A-16

CHIPPERS

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59+60 R. 26 4 Mer.

E 1/16 Corner common to Sections

3, and 34

Corner consists of a Cedar st. (not) in place

State condition

Dimensions above ground 50 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No


If not, why? U.S.F.S.

George H. ... (Signature)

11-18-35 (Date)

(Title)

Metal Location Poster is on a *W Cedar*
 tree 12 inches diameter, on the *East*
 side of *tree*
 from which this Corner bears *N 78 E*
 0.12 chains distant.
 Give any further facts which will aid in finding this
 Corner again.
Poster on old line tree



(Make sketch of topography near Corner)