

U. S. Department of Agriculture

FOREST SERVICE

posted E-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *59* R. *28* Mer.

Corner common to Sections *10, 11, 12, and 13*



Corner consists of a *laminated stone* (not) in place
State condition *good*

Dimensions above ground *40" x 1 1/2"* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species	<i>Birch</i>	<i>Cedar</i>	<i>Birch</i>	<i>Birch</i>
Diameter	<i>5"</i>	<i>22"</i>	<i>6"</i>	<i>6"</i>
Bearing	<i>N 80° W</i>	<i>N 35° E</i>	<i>S 25° W</i>	<i>S 30° W</i>
Distance	<i>.25 ch</i>	<i>.25 ch</i>	<i>.45 ch</i>	<i>.45 ch</i>

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

E. Rammell
(Signature)

Oct 25, 1913
(Date)

Surveyor
(Title)

Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.

1/2 mile north of ...
1/2 mile ...
1/2 mile ...

	Sec.		Sec.
		<i>Little ...</i>	
	Sec.		Sec.

(Make sketch of topography near Corner)

T. 59 R. 26 Mer.

posted
E-17

Shippensburg NATIONAL FOREST


CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 4 Mer.

Section Corner common to Sections
3, 2, 11, and 10

Corner consists of a Stake in place
State condition Good

Dimensions above ground three ft inches
Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>2</u>	<u>3</u>	<u>10</u>	<u>11</u>
<u>BT</u>	<u>BT</u>	<u>BT</u>	<u>BT</u>

Species Ledger Birch Birch Birch

Diameter N 85 E N 65 W S 17 E S 30 W

Bearing _____

Distance 16 ft 14 ft 20 ft 25 ft

Do you believe this to be a genuine Land Office Corner? _____

If not, why? yes


John Cochran
(Signature)

10-24
(Date)

Forest Ranger
(Title)

Section 1 of T. 12 N. 36 E. 35 R. 1 W.
Corner again

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 12 N. 36 E. 35 R. 1 W. Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa

NATIONAL FOREST

E717

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th Mer.

Section Corner common to Sections
2, 3, 10, and 11Corner consists of a Pine post (not) in place
iron pin (triangular)


State condition Good

Dimensions above ground 40" x 12" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S3

S11

S2

BT

BT

BT

Species W. Birch W. Birch W. Cedar

Diameter 4 5 10

Bearing N72W 540E N70E

Distance 0.28 0.43 0.37

Do you believe this to be a genuine Land Office Corner? Prob.

If not, why? Cor. re-established by Co

George J. Johnson

(Signature)

10-18-35

(Date)

Jr. Foreman C.M.

(Title)

Bearing first

Corner again.

Give any further facts which will aid in finding this


chains distant. *0.37*

from which this Corner bears *570W*

side of *tree*

tree 10 inches diameter, on the *SW*

Metal Location Poster is on a *W. Cedar*



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

E-17P

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th Mer.

Section 2, 3, 10, and 11 Corner common to sections


Corner consists of a Pine Post (not in place) State condition Good Iron pin (triangular)

Dimensions above ground 40" & 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Birch W. Birch W. Cedar

Diameter 4 5 10

Bearing N72W S40E N70E

Distance 0.28 0.43 0.37

Do you believe this to be a genuine Land Office Corner? Prob

If not, why? Corner re-established by Co.

George H. Jennings

(Signature)

Jr. Foreman C & M

10-18-35

(Date)

(Title)

Corner again.
Bearing tree

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears $0^{\circ}37'$
S70W

side of tree

tree inches diameter, on the

Metal Location Poster is on a ¹⁰W. Cedar



(Make sketch of topography near Corner)