

U. S. Department of Agriculture
FOREST SERVICE

V-19

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 59N. R. 26W. 4th Mer.

1/4 Corner common to Sections
26, and 35

Corner consists of a 9" spruce post (now iron pipe) in place
State condition good

Dimensions above ground post 36" pipe 8 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION				DIAGONAL POSITION			
S 26		S 35					
N	W	S	E	NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 26		S 35	
B.T.		B.T.	

Species *W. pine* *aspn*
Diameter *36"* *5 in.*
Bearing *N. 7° W.* *S. 66° E.*
Distance *61 links* *49 li.*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why?

BT's not LLO SWP 8/30/27


Ernest Perry
(Signature)

Field Ass't
(Title)

9-27-34
(Date)

Corner again.
 CORNER IS LOCATED ON THE
 SIDE OF SMALL ALDER SWAMP,
 PLACED USES POSTER ON S
 POISON AT INTERSECTION OF BIG
 OLE'S TRAIL AND SECTION LINE
 COMMON TO S. 26-535-5.32 EAST
 OF 4526-535

Give any further facts which will aid in finding this
 12. ~~links~~ ~~chains~~ ~~diagram~~.
 from which this Corner bears N. 54° E.
 side of tree
 tree 8. inches diameter, on the East
 Metal Location Poster is on a ASPEN



(Make sketch of topography near Corner)

T. 59N R. 26W 4th Mer.