

**U. S. Department of Agriculture**  
**FOREST SERVICE**

*Chippewa* NATIONAL FOREST *U-11*

**CORNERS OF THE PUBLIC SURVEY**

T. *59 N* R. *26 W* *4th* Mer.

CS (# *6*) *1/16* Corner common to Sections  
-----, -----, *28*, and -----

Corner consists of a *4" cedar* (not) in place

State condition *good* (*1" iron pipe 6"*)

Dimensions above ground *3'* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	# <i>6</i>		# <i>6</i>
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	# <i>6</i>		# <i>6</i>
	<i>BT</i>		<i>BT</i>

Species ----- *aspen* ----- *aspen*

Diameter ----- *5"* ----- *4"*

Bearing ----- *N 33° E* ----- *S 51° E*

Distance ----- *51 Li* ----- *35 Li*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? -----

*Erwin Meagher*  
(Signature)

*1-7-35*  
(Date)

*Field Ass't*  
(Title)

Hand Level, Second  
growth ASPEN

Corner again.

Give any further facts which will aid in finding this


35 ft. ~~obscure~~ distant.

from which this Corner bears N. 51° W.

side of tree

tree 4 inches diameter, on the N. W.

Metal Location Poster is on a ASPEN



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4th Mer.