

U. S. Department of Agriculture
FOREST SERVICE

F-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th P Mer.

NC 416 Corner common to Sections
12, and

Corner consists of a Aspen stake (~~not~~) in place
State condition

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? U.S.F.S

10-7-35

(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.82

from which this Corner bears

N48W

side of


tree

tree 6 inches diameter, on the

NW

Metal Location Poster is on a

V. Pine



(Make sketch of topography near Corner)

T. R. Mer.