

U. S. Department of Agriculture

FOREST SERVICE

A-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 2 P Mer.

1/4

Corner common to sections

1, and 36-60-26

Corner consists of a Pine Post (not) in place


State condition

Dimensions above ground 40 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



1/2 51



1/4 536



BT



BT

Species J. Pine J. Pine

Diameter 12 12

Bearing S361Y N60E

Distance 0.10 0.41

Do you believe this to be a genuine Land Office Corner? No

If not, why? Probably Co. Y & LO

(Signature)

12-10-35

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.10

from which this Corner bears

N36E

side of


tree

tree 12 inches diameter, on the

NE

Metal Location Poster is on a

J.P.C. B.T.



(Make sketch of topography near Corner)

T. 59 R. 26 Mer. A P

U. S. Department of Agriculture
FOREST SERVICE

A-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59+60 N. R. 26 W. 4th Mer.

1/4 Corner common to Sections

1-59-26, and 36-60-26

Corner consists of a 3" scribed Post (not) in place

State condition Poor

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

453		1/4 51	
T 60 N		T 59 N	
R 26 W		R 26 W	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 51
T 59 N
R 26 W

1/4 5 26
T 60 N
R 26 W

BT

BT

--

--

Species J. Pine J. Pine

Diameter 10" 12"

Bearing S 36° W N 63° E

Distance 10.143 42.143

Do you believe this to be a genuine Land Office Corner? No

If not, why? Evidently set by County Surveyor


Arthur J. Johnson
(Signature)

Squad Foreman
(Title)

3/5/190
(Date)

Corner again.
Scribed Post/Leaning against S.W. B.T.
2" x 36" Approx. Hagen Post in Place

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 59460N R. 26W 47th Mer.