

## U. S. Department of Agriculture

FOREST SERVICE

E-24

Chippewa

NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th Mer.

E 116

Corner common to Sections

1, and 12

Corner consists of a Cedar stake (not) in place

State condition

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner?  No

If not, why? U.S.F.S

(Signature)

10-7-35  
(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears *N60W*

side of *tree*

*4* inches diameter, on the *NW*

Metal Location Poster is on a *B. of Forest*



(Make sketch of topography near Corner)

T. R. Mer.