

U. S. Department of Agriculture
FOREST SERVICE

N-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 52 N R. 27-26 W 4th Mer.

Sec Corner common to Sections
13, 18, 19, and 24

Corner consists of a post (~~not~~) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

<u>S13</u>	<u>S24</u>	<u>S19</u>	<u>S18</u>
------------	------------	------------	------------

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>S</u> <u>13</u>	<u>S</u> <u>24</u>	<u>S</u> <u>19</u>	
<u>B.T.</u>	<u>B.T.</u>	<u>B.T.</u>	

Species SPY ASP ASP

Diameter 11" 7" 12"

Bearing N4°W S16°W S43°E

Distance 0.51 0.50 0.53

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

E. A. Sogren

(Signature)

12/20-34

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 59 R. 27-26 Mer. 4