

U. S. Department of Agriculture
FOREST SERVICE

G-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W - 25 4th P. Mer.

Quarter Corner common to Sections



12, and 7
Corner consists of a ~~2"x6"~~ scribed post above gr. (not) in place
State condition Good Ir. Pipe

Dimensions above ground Post 40 Ir. Pipe 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig.	Brs.		
S 7	S 12		
B.T.	B.T.		

Species	N. Pine	N. Pine	_____
Diameter	14"	12"	_____
Bearing	N14°E	N58°W	_____
Distance	69	23½	_____

Do you believe this to be a genuine Land Office Corner? **Yes**


If not, why? _____

J. A. Gjelhaug
(Signature)

6/24/37
(Date)

Jr. Civil Eng.
(Title)

Metal Location Poster is on a N. pine tree 14 inches diameter, on the South side of tree from which this Corner bears 9140' 0.69 chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

G-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 4 Mer.

E 1/4 Corner common to Sections

12, and 7, 59-25

Corner consists of a 4" Post (New cedar put in) (not) in place

State condition Broken off

Dimensions above ground 36 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

44
5
12

W 1/4 S 7

13 T

BT

Species N. Pine N. Pine

Diameter 10" 14"

Bearing N 64 W N 5 E

Distance 0.23 0.69

Do you believe this to be a genuine Land Office Corner?

If not, why? Not Old enough.


N. Pine Bearing Tree 14" Dia

has Scribing W 1/4 Cor. Sec. 7

Murbeck & Niebuhr,
(Signature)

1-7-37
(Date)

(Make sketch of topography near Corner)



Metal Location Poster is on a

tree 14 inches diameter, on the S_o,

side of ^{TRAP}

from which this Corner bears

S 5 W

0.69 chains distant.

Give any further facts which will aid in finding this

Corner again.

CORNER 150 CHS. W. OF LAKE CLUB

(House)

N. Pine, Birch, Alder

Poster on N. Pine 10"
East side, 0.22.50 Chs

T. 59 R. 26 N. 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

G-25

Chipewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 4 Mer.

E 1/4 Corner common to Sections

12, and 7, 59-25

Corner consists of a 4" Post. *New Cedar put in.* (not) in place


State condition *BROKEN OFF*

Dimensions above ground *36* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



BT

BT

Species *N. Pine* *N. Pine*

Diameter *10"* *14"*

Bearing *N 64 W* *N 5 E*

Distance *23 /ks* *69 /ks*

Do you believe this to be a genuine Land Office Corner? *Y*

If not, why? *Not old enough*

N. Pine Bearing Tree 14" Dia

has Scribing W 1/4 Cor. Sec. 7

MURBECK + Niebuhr

(Signature)

1-7-37
(Date)

(Title)

Poster on N. Pine, 10"
East Side, 0.2250 Chs

N. Pine, Birch, Alder

(Hause)

Corner 1.50 Chs W. of Lake Club-

Corner again.

Give any further facts which will aid in finding this


0.69 chains distant.

from which this Corner bears S. 5 W

side of

tree 14 inches diameter, on the So.

Metal Location Poster is on a N. Pine



(Make sketch of topography near Corner)

T. 59 R. 26 Mer. 474