

U. S. Department of Agriculture

FOREST SERVICE

A-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59+60N R. 25+26W 4th Mer.

T.W.P. Corner common to Sections

1-59-26, 6-59-25, 31-60-25 and 36-60-26

Corner consists of a 2" Iron Pipe with Cap (not) in place

State condition Good

Dimensions above ground Post 30 Pipe 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

536	51	56	531
T60N	T59N	T59N	T60N
R26W	R26W	R25W	R25W

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

ST T. 59N R. 26W			
BT			

Species R. Pine 25b

Diameter 19"

Bearing S 35° W

Distance 151k

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Set by County from B.L.O. B.T's one of which remain

Arthur J. Johnson

(Signature)


Squad Foreman

(Title)

3/1/40
(Date)

(Make sketch of topography near Corner)

T.59760N R.25426W 915 Mer.



Metal Location Poster is on a dead W. Pine

tree 80 inches diameter, on the NW

side of Tree

from which this Corner bears N60°W

79 chains distant.

Give any further facts which will aid in finding this

Corner again.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 & 25 of Mer.

Section 1, 6
Corner common to sections

and
Corner consists of a *pine post* (not) in place

State condition *Good*

Dimensions above ground *40 x 6* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

N	W	S	E

DIAGONAL POSITION

NW	SW	SE	NE
7594 7594 7594 7594	7594 7594 7594 7594	7594 7594 7594 7594	7594 7594 7594 7594

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

(Date)

8-7384

(Title)

(Signature)


Henry H. ...

19-11-25

A-25

T. 59 R. 26 4 P Mer.

(Make sketch of topography near Corner)



Metal Location Poster is on a Pine stub E.T.
tree 12 inches diameter, on the W
side of the stub
from which this Corner bears N 50° E
0.15 chains distant.

Give any further facts which will aid in finding this
Corner again.

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th -- Mer.

Corner common to Sections

1, 6, 36, and 30 stake

Corner consists of a Pine W stake (not) in place

State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		<u>R26W</u> <u>51</u>	

Species Pine Stake

Diameter 12

Bearing S75W

Distance 0.15

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)

12-6-35

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

D. 12

from which this Corner bears


N 25 E

side of *tree*

tree 12 inches diameter, on the

NE

Metal Location Poster is on a *W. B. King's Sub (B.T.)*



(Make sketch of topography near Corner)

T. R. Mer.

U. S. Department of Agriculture

FOREST SERVICE

A-25
Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 4P Mer.Section Corner common to Sections36, 1, 6, and 31Corner consists of a Slide Post (not) in placeState condition GoodDimensions above ground 40 x 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

T60N	T59N	T59N	T60N
R26W	R26W	R25W	R25W
536	51	56	531

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		9N 26W 51	

Species _____ Pine stubDiameter _____ 12"Bearing _____ N25EDistance _____ 0.15

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

George Jennings

(Signature)

10-10-35

(Date)

Jr. Foreman C&M

(Title)

RECEIVED
JUL 7 1936

Corner again.

Give any further facts which will aid in finding this


0.15 chains distant.

from which this Corner bears N25.E

side of Stake

tree 12 inches diameter, on the NE

Metal Location Poster is on a Pine Stake BT



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

*posted
A-25*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. _____ R. _____ Mer. _____

_____ Corner common to Sections _____, _____, _____, and _____

Corner consists of a _____ (not) in place State condition _____

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<i>Tree</i>		<i>Tree</i>
	<i>Tree</i>		<i>Tree</i>

Species _____ *White*

Diameter _____ *12"*

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

James W. Campbell

(Signature)

Oct 25

(Date)

app.

(Title)

Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. 59 R. 25 Mer.