

U. S. Department of Agriculture

FOREST SERVICE

*posted*

*Chippewa* NATIONAL FOREST

QR-21

CORNERS OF THE PUBLIC SURVEY

T. *59* R. *26* *4<sup>th</sup>* Mer.

*Meander*

Corner common to Sections

and *23-24*

Corner consists of a *iron pin* (not) in place

State condition *Good*

Dimensions above ground *12"* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Birch* *Pinestems* *Birch*

Diameter *8"* *12"* *9"*

Bearing *W.* *W 22° S* *N. 10° E*

Distance *17 1/2* *21 1/2* *41 1/2*

Do you believe this to be a genuine Land Office Corner? *Yes.*

If not, why? \_\_\_\_\_

*Walter Pelraske*

(Signature)

*10/24/33*

(Date)

*Est.*

(Title)

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R. Mer.

U. S. Department of Agriculture  
FOREST SERVICE

Q.R-21

P

CHIPPEWAGON NATIONAL FOREST

Q.R-21

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4<sup>th</sup> Mer.

MC

Corner common to Sections

23, 24, 25, and 26

Corner consists of a 1" iron pipe (not) in place

State condition

Dimensions above ground 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--

MC  
23

--

--

BT

1BT

--

--

Species WP LINC Birch

Diameter 10" 5"

Bearing N 76° W S 81° W

Distance 20.1 Ks 17.1 Ks

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

K. L. P. (Signature)

10/12/35 (Date)

(Title)

Corner sets on N  
shore of Big Island  
take about 150' W of  
summer cottage

Corner again.

Give any further facts which will aid in finding this


271K3 chains distant.

From which this Corner bears 570'E

side of tree

tree 5 inches diameter, on the SE

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 59N R. 26W 4th Mer.

U. S. Department of Agriculture  
FOREST SERVICE

O, R-21

*chippenaw* NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4<sup>th</sup> Mer.

MC Corner common to Sections  
23, 24, 25, and 26

Corner consists of a 1" iron pipe (not) in place  
State condition \_\_\_\_\_

Dimensions above ground 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N      W      S      E

--	--	--	--

NW   SW   SE   NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	MC 23		
BT	BT		

Species W pine BTDiameter 10" 5"Bearing N76°W 581°WDistance 201Ks 171KsDo you believe this to be a genuine Land Office Corner? Yrs

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Kling  
(Signature)

10/12/33

(Date)

(Title)

Corner sets on N  
shore of Big Island  
take about 150' W of  
summer cottage

Corner again.

Give any further facts which will aid in finding this


271Ks chains distant.

from which this Corner bears S 70° E

side of tree

tree 5 inches diameter, on the SE

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 59N R. 26W 4th Mer.

U. S. Department of Agriculture  
FOREST SERVICE

9, R-21

shippahonk NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th Mer.

MC Corner common to Sections  
23, 24, and

Corner consists of a 1" IRON PIPE (not) in place  
State condition

Dimensions above ground 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	MC		
	23		
BT	BT		

Species White o Birch o

Diameter 10" o 5" o

Bearing N76W o 581°W o

Distance 201ks o 171ks o

Do you believe this to be a genuine Land Office Corner? YPS

If not, why?

K. B. G.  
(Signature)

10/12/35  
(Date)

(Title)

CORNER STAKES ON N  
SHORE OF BIG ISLAND  
LAKE ABOUT 150' W  
OF SUMNER COLLEGE

Corner again.

Give any further facts which will aid in finding this


271K's chains distant.

From which this Corner bears 570° E

side of line

tree 5 inches diameter, on the SE

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 59 N. R. 26 W. 4th Mer.