

U. S. Department of Agriculture
FOREST SERVICE

S-10, 11

SHIPPENAW NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

MEANDER Corner common to Sections
....., and 28


Corner consists of a Cedar Post 2" x 4" (not) in place
State condition Good

Dimensions above ground 24" - 6" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Mc
N 1/4
LINE

Mc
N 1/4
LINE

B.T.

B.T.

Species Balm. Balm.

Diameter 12" 11"

Bearing N 15° W S 48° E

Distance 18.1 ks 59.6 ks

Do you believe this to be a genuine Land Office Corner? No

If not, why? County scribbling
on post - bearing trees.

MUTBECK
(Signature)

10-18-38
(Date)

(Title)

Corner again.
Post on bank at edge of lake
Cabin about 2 chs. S.E. corner.


Give any further facts which will aid in finding this
-16- chains distant.

From which this Corner bears S 35.5 E

side of TREE

tree 5 inches diameter, on the S.E.

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 59N R. 26W Mer.

U. S. Department of Agriculture
FOREST SERVICE

S
10, 11

Shippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W. 4th Mer.

Mander Corner common to Sections
, and 28

Corner consists of a cedar post 2"x4" (not) in place
State condition Good


Dimensions above ground 24 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Balm Balm 1

Diameter 11" 12"

Bearing S 48° E N 15° W

Distance 59 LKS 18 LKS.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? County scribbling on post + BEARING TREES

Meyer
(Signature)

13-18-38
(Date)

(Title)

Post is on bank at edge of lake
Cabin about 2 chs. SE of corner.

Corner again.

Give any further facts which will aid in finding this


1/6 chains distant.

From which this Corner bears S 35° E

side of T T F F

tree 5 inches diameter, on the SE

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)