

U. S. Department of Agriculture  
FOREST SERVICE

*posted*  
*ST-17*

*Shippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 R. 26 Mer. 4

M.C. Corner common to Sections  
26, and 27


Corner consists of a stone iron pipe (not) in place  
State condition good

Dimensions above ground 1" x 1 1/2" (iron pipe) inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen Aspen

Diameter 6" 9"

Bearing N 60° E west

Distance 4 ft. 15 ft.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*J. M. Bengall*  
(Signature)

10/24/53  
(Date)

(Title)

-----

-----

-----

-----

-----

-----

-----


-----

-----

-----

Corner again.

Give any further facts which will aid in finding this  
 ----- chains distant.  
 from which this Corner bears  
 ----- side of  
 tree ----- inches diameter, on the  
 Metal Location Poster is on a -----



(Make sketch of topography near Corner)

T. R. Mer.