

U. S. Department of Agriculture
FOREST SERVICE

T-10-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

M. C. Corner common to Sections
28, and

Corner consists of a 4" cedar (not) in place

State condition good 1" iron pipe 6"

Dimensions above ground 5 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____ W. Birch W. Birch
 Diameter _____ 4" 5"
 Bearing _____ N 76° E S 53° E
 Distance _____ 47 L. 23 L. ⑥

Do you believe this to be a genuine Land Office Corner? yes
 If not, why? _____

Erwin Meagher
 (Signature)
1-8-35 Field ass't
 (Date) (Title)

Corner again.
 The B.T.S. and corner post
 are not scribed
 Land Polling Second
 growth W. Birch


Give any further facts which will aid in finding this

231.1 ~~chords~~ distant.

From which this Corner bears
 N 53. W

side of tree

Metal Location Poster is on a W. Birch
 tree 5 inches diameter, on the N.W.



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4th Mer.