

Camp  
057

U. S. Department of Agriculture

FOREST SERVICE

J,K-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26-25 4<sup>th</sup> Mer.

Meander Corner common to Sections

~~12~~, ~~13~~ 18, and

Corner consists of a 4" Post (not) in place


State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N. Pine

Diameter 12

Bearing S51°30'E

Distance 114 lks

Do you believe this to be a genuine Land Office Corner? <sup>Ⓢ</sup> No

If not, why? County scribing on Post

+ bearing trees

Murbeck - Niebuhr

(Signature)


1/6/37

(Date)

(Title)

Corner again.  
Meadow corner located on  
south shore of Club House Lake.  
Aspen - Birch type

Give any further facts which will aid in finding this  
Corner again.  
8.50 lks ~~east~~ distant.  
from which this Corner bears  
S 74 W  
side of Tree  
tree 4 inches diameter, on the West  
Metal Location Poster is on a  
Birch



(Make sketch of topography near Corner)

Supervisor  
copy

U. S. Department of Agriculture

FOREST SERVICE

J, K-25

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 4<sup>th</sup> Mer.

Remained Corner common to Sections  
12, 13, 18, and


Corner consists of a 4" Post (not) in place  
State condition Good

Dimensions above ground 30 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N. Pine

Diameter 12

Bearing S 51° 30' E

Distance 114 lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Sounding scribbled on Post and bearing trees

Murbeck - Niebuhr

(Signature)


1/6/37

(Date)

(Title)

(Make sketch of topography near corner)

T. 59 R. 26 Mer. 4th



Metal Location Poster is on a Birch

tree 4 inches diameter, on the West

side of tree

from which this corner bears S 74 W

8.50 JKS chains distant.

Give any further facts which will aid in finding this

Corner again.

Aspen - Birch tree

meadow cor. located on S. shore

Club House Lake