

U. S. Department of Agriculture
FOREST SERVICE

5-15

OLYMPIA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59E R. 27N Mer.

Corner common to Sections
10, and 15

Corner consists of a _____ (not) in place


State condition _____

Dimensions above ground _____ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N. Pine Cedar

Diameter 10" 7"

Bearing 815 810

Distance 1.62 0.66

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

D. Peck

(Signature)

CGC Mueller

(Title)

3-26-35

(Date)

Dotted lines for notes.

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.66


from which this Corner bears

S20E

side of Tree

tree 7 inches diameter, on the SE

Metal Location Poster is on a Cedar (BT)



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

5-15

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 52N R. 27W Mer. 4

1/4 Corner common to Sections
10, and 15

Corner consists of a _____ (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u> <u>S 15</u>

<u>1/4</u> <u>S 10</u>

--

--

<u>BT</u>

<u>BT</u>

--

--

Species W. Pine Cedar

Diameter 10" 7"

Bearing S 36W N 20W

Distance 1.62 0.66

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


D. Roale
(Signature)

3-26-35
(Date)

C.C.C. Envallee
(Title)

Metal Location Poster is on a *Cedar (BT)* tree *7* inches diameter, on the *SE* side of *Tree* from which this Corner bears *520 E* *SE* chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 59N. R. 27W. 4 Mer. J-15

U. S. Department of Agriculture
FOREST SERVICE

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY ⁵¹⁵

T. 59N R. 27W 4 Mer.

$\frac{1}{4}$ Corner common to Sections
10, and 15

Corner consists of a _____ (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$ S15

$\frac{1}{4}$ S10

--

--

BT

BT

--

--

Species W. Pine Cedar

Diameter 10" 7"

Bearing S36W N20W

Distance 1.62 0.66

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? _____

D. Poole

(Signature)


3-26-35

(Date)

CCC Enrollee

(Title)

Metal Location Poster is on a **Corner (NE)** tree **7** inches diameter, on the **SE** side of **Tree** from which this Corner bears **0.56** chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)