

Supervisor copy

U. S. Department of Agriculture
FOREST SERVICE

P

Chippewa NATIONAL FOREST

2/6

CORNERS OF THE PUBLIC SURVEY

T. ⁵⁹58 N. R. 27 W., 4th Mer.

E. ¹¹⁶116 Corner common to Sections
34, and 3

Corner consists of a 1" iron pipe (not) in place

State condition good - has scribed guard stake

Dimensions above ground 4 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	1/16		1/16
	S		S

IBR N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

65			
			T

Species Balm Gilead Birch

Diameter 14" 16"

Bearing N17°W S21°W

Distance 0.28 chs 0.24 chs

Do you believe this to be a genuine Land Office Corner? No

If not, why? Evidently established by county surveyors.

Charles J. Knoblauch

(Signature)

Junior Forester

(Title)

July 23, 1937
(Date)

