

Form 874-0—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

E-20

NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 59 R. 27 Mer. 4  
E 1/16 Corner common to Sections

2, and 11

Corner consists of a poplar (not in place)

State condition good

Dimensions above ground \_\_\_\_\_ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? NO

If not, why? \_\_\_\_\_

No corner but a tree blazed on 4 sides.


J. H. Hamelain  
(Signature)

12-11-39  
(Date)

ccc  
(Title)

Handwritten notes on a set of horizontal lines.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)