

U. S. Department of Agriculture
FOREST SERVICE

10-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *59 N* R. *27 W* *4th* Mer.

Sec Corner common to Sections

11, *12*, *13*, and ~~*14*~~

Corner consists of a *Cedar Post* (not) in place

State condition ~~*Decayed*~~ *Decayed - Down*

Dimensions above ground ~~*5*~~ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

<i>511</i>	<i>514</i>	<i>513</i>	<i>512</i>
------------	------------	------------	------------

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		<i>R27W</i>	
		<i>S13</i>	
		<i>BT</i>	

Species *SPRUCE* _____

Diameter *20"* _____

Bearing *S58°E* _____

Distance *34* _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

E.A. Sagen
(Signature)

12/19/34
(Date)

(Title)

Corner again.


Give any further facts which will aid in finding this chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

J-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 27 W 4th Mer.

SEC

Corner common to Sections

11, 12, 13, and 14

Corner consists of a Cedar Post in place

State condition Decade

Dimensions above ground Down inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S 11	S 14	S 13	S 12
------	------	------	------

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		R 27 W	
		S 13	
		BT	

Species Spruce

Diameter 20"

Bearing S 58° E

Distance 34

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

EA Dagen (Signature)

12/19/34 (Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

posted

24100 E W 1/4 NATIONAL FOREST

J 21

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 27 Mer. 426

Section 11, 12, 13, and 14 Corner common to Sections

Corner consists of a stone (not) in place
State condition stone

Dimensions above ground _____ inches.
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

<u>11</u>	<u>14</u>	<u>13</u>	<u>12</u>
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>20</u>			

Species Red Pine

Diameter 12"

Bearing E. 65 S

Distance 24'

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

RETINER

(Signature)

11/7/23

(Date)

Retiner

(Title)

Metal Location Poster is on a _____ inches diameter, on the
 side of _____ from which this Corner bears _____ chains distant.
 Give any further facts which will aid in finding this
 Corner again.

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)