

Form 8749 - Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

12-4

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N. R. 27 W. 4th Mer.

S/16

Corner common to Sections

11, and 12

Corner consists of a squared stake (not) in place

State condition good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? _____

This is an approximate corner, set up by CCC employees.

H. Hamelain

(Signature)

12-4-39


(Date)

CCC

(Title)

This corner is approximately
8 chs west of the break.
Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)