

U. S. Department of Agriculture
FOREST SERVICE

CHIPPewa NATIONAL FOREST

N23

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 27W 4 Mer.

1/4 Corner common to Sections
13, and 24

Corner consists of a Tim (~~rock~~) in place


State condition Good

Dimensions above ground 30 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



BT

BT



Species Sp As (Stump)

Diameter 6" 14"

Bearing S45W N22'30'E

Distance 0.78 0.73

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Sagen

(Signature)

CCC Enrollee

(Title)

2-11-35

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.29

from which this Corner bears

N27W

side of


Tree

tree 7 inches diameter, on the

NW

Metal Location Poster is on a

Aspen



(Make sketch of topography near Corner)

T. 59N

R.

R27W

4

Mer.

N-23